

CASE STUDY | PROFESSIONAL



HIGH-RISE BUILDING INTERIORS

NAPLES, FLORIDA

During this construction project, due to rainy conditions, interior crews were installing drywall faster than exterior crews could enclose it.

Cinder blocks and exposed drywall were absorbing wind-driven rain like a sponge. Since the drywall retained the water, a mildew problem arose.



DRYLOK®

MASONRY WATERPROOFER

● ● To combat the elements and keep the interiors dry, the inside of the exterior walls were coated with DRYLOK® Original Masonry Waterproofer.



UGL® UNITED GILSONITE LABORATORIES

1-800-845-5227 • www.UGL.com

Corporate Office: 1396 Jefferson Avenue, Dunmore, PA 18509

Mail to: P.O. Box 70, Scranton, PA 18501-0070

Plant Locations: Jacksonville, IL • Jackson, MS

