

CASE STUDY | PROFESSIONAL



BMW® TIEXI PLANT CHINA

The facility wanted to protect the below grade space, about 40,000 sq. ft. As the walls were relatively smooth with hairline cracks, no patching was required.



DRYLOK®

- After a thorough cleaning, two coats of DRYLOK® Extreme Masonry Waterproofing were applied to the walls, three coats in some sections. Once the walls were treated, DRYLOK® Latex Concrete Floor Paint was used on the floor. After it dried, DRYLOK® WetLook High Gloss Sealer was applied. By controlling dust, dirt and moisture, our products contributed significantly to an improvement in air quality.

UGL® UNITED GILSONITE LABORATORIES

1-800-845-5227 • www.UGL.com

Corporate Office: 1396 Jefferson Avenue, Dunmore, PA 18509

Mail to: P.O. Box 70, Scranton, PA 18501-0070

Plant Locations: Jacksonville, IL • Jackson, MS

